



Physical Address: 8812 Hwy 79 West Jewett, TX 75846 (903) 626-4461

Mail Address: POB 126 Jewett, TX 75846 Fax (903) 626-6293

January 28, 2016

Environmental Protection Agency
Office of Enforcement and Compliance Assurance
Office of Federal Activities
International Compliance Assurance Division (2254A)
1200 Pennsylvania Avenue, N.W.
Washington, D.C. 20460

Re: Annual Hazardous Waste Export Report

Nucor Steel - Texas

EPA ID #: TXD071378582

Dear Sir or Madame:

In accordance with 40 C.F.R \S 262.56, Nucor Steel – Texas is submitting its 2015 Annual Hazardous Waste Export Report.

Please contact Matt Way at (903) 626-4461 if you have any questions.

Sincerely,

Thad Solomon GM and VP

Enclosure

cc: TCEQ

Executive Director

| Son 1/21/2016

2015 ANNUAL HAZARDOUS WASTE EXPORT REPORT

1. Exporter

EPA ID #: TXD071378582

Name: Nucor Steel Company Site Address: 8812 Hwy 79 West

Mail Address: PO Box 126

City: Jewett State: Texas Zip Code: 75846

2. Calendar Year

Year: 2015

3. Consignee

Name: Zinc Nacional, S.A.

Address: Serafin Peña 938 Sur, Adpo. Postal 3062

Monterrey, N.L. Mexico 64000

4. Waste Information

Description: Emission control dust/sludge from the primary production of steel

in electric furnaces

EPA Waste #: K061

DOT Info: UN3077, Waste Environmentally Hazardous Substance, Solid,

N.O.S., Class 9, PG III (K061)

Transporter(s): Union Pacific Railroad

EPA ID#: NED001792910

Waste Shipped: 12,937.45 tons

of Shipments: 132 railcar loads

5. Waste Reduction/Minimization Statement

Nucor continues to strive to reduce the amount of waste, either solid or hazardous, generated through its waste minimization program. The facility and its ancillary equipment are inspected often to insure compliance with all applicable State and Federal regulations, equipment is maintained and kept in good operating condition, and waste material is kept enclosed whenever possible. Due to the electric arc furnace process, the quantity of emission dust generated is dependent upon the amount of steel generated. However, Nucor continues to test and implement new technologies to reduce, minimize and recycle the waste generated.

Nucor has continued several waste minimization projects during 2015. These included better process control of the electric arc furnace to minimize the amount of material being generated as K061 as well as a recycling process for its drop-out box material to again minimize the amount and toxicity of K061 being generated. Nucor was able to keep the generation rate low at 32.50 lbs K061/ton of steel cast in 2015. The amount of dust generated can vary with scrap mixes and scrap quality. In 2014, the generation rate was 30.82 lbs/ton.

In addition, emission dust is sent off-site to the above facility for the purpose of recorvering metals and other compounds for sale as primary products. The recovery processes are able to convert all of the emission control dust into viable commodities, eliminating disposal of material that is sent off-site for recovery. Recovery of the metals and other compounds preserves natural resources and reduces wastes generated from other industries (i.e., smelting operations).

6. Certification

I certify under penalty of law that I have personally examined and am familiar with the information submitted in this and all attached documents, and that based on my inquiry of those individuals immediately responsible for obtaining the information, I believe that the submitted information is true, accurate, and complete. I am aware that there are significant penalties for submitting false information including the possibility of fine and imprisonment.

Signature:

_____ Date: 1/28/2016



After printing this label: 1. Use the 'Print' button on this

Use the 'Print' button on this page to print your label to your laser or inkjet printer.

2. Fold the printed page along the horizontal line.

3. Place label in shipping pouch and affix it to your shipment so that the barcode portion of the label can be read and scanned.

Warning: Use only the printed original label for shipping. Using a photocopy of this label for shipping purposes is fraudulent and could result in additional billing charges, along with the cancellation of your FedEx account number.

Use of this system constitutes your agreement to the service conditions in the current FedEx Service Guide, available on fedex.com.FedEx Service Guide, available on fedex.com.FedEx Service Guide apply. Your right to recover from FedEx to any loss, including intrinsic value of the package, whether the result of loss, damage, delay, non-delivery, imisdelivery, or misinformation, unless you declare a higher value, pay an additional charge, document your actual loss and file a timely claim.Limitations of found in the current FedEx Service Guide apply. Your right to recover from FedEx for any loss, including intrinsic value of the package, loss of sales, income interest, profit, attorney's fees, costs, and other forms of damage whether direct, incidental, consequential, or special is of sales, income interest, profit, attorney's fees, costs, and other forms of damage whether direct, incidental, consequential, or special is extraordinary value is \$1,000, e.g. jewelry, precious metals, negotiable instruments and other items listed in our ServiceGuide. Written extraordinary value is \$1,000, e.g. jewelry, precious metals, negotiable instruments and other items listed in our ServiceGuide. Written claims must be filed within strict time limits, see current FedEx Service Guide.